

# SE 708 Firmware Update

App Note Number: 265

Affected Products	SE 708
Support Reference	N/A
Audience	Operations, Customers, Partners
Date	4 <sup>th</sup> March 2025
Supersede	262
Severity	Low – Firmware Upgrade

## Background

---

SE 708 version 2.901 has been released to the Speakerbus Fast Track release stream to resolve the following defect as detailed below.

### Defects Resolved in Version 2.901

- No RTP Media in Recording Streams on Incoming Group Calls when SE708 is in Remote Hosted mode (SB-8010).

## Next Steps

---

To upgrade your SE 708 to 2.901 please contact your regional Speakerbus account representative for guidance on how to obtain the firmware.

Once the firmware has been downloaded to your server, please use iCMS to initiate a firmware download to the device and wait for the upgrade to 2.901.1.0 to complete.

If you have any questions regarding this communication, please contact Speakerbus Global Customer Support (<https://www.speakerbus.com/helpdesk>).

End of Application Note 265.